MEMORANDUM

July 10, 2019

TO: Reclamation District No. 756

FROM: Nathan Hershey, Mike Kynett

SUBJECT: July 2019 Engineer's Report

Described below are the engineering items to be discussed at your July 10, 2019 meeting.

Subventions 2017-18 – The District submitted an application for participation in the Program in the amount of \$900,000. \$14.5 million has been approved for Program funding for FY 2017-18. The District's final claim was submitted in the amount of \$415,760.88. Reimbursement has been received in the amount of \$292,267.00.

Subventions 2018-19 – The District submitted an application for participation in the Program in the amount of \$845,000. \$12 million has been approved for Program funding for FY 2018-19, consistent with recent previous years.

Subventions 2019-20 – The District submitted an application for participation in the Program in the amount of \$750,000. DWR has lowered the Program funding amount to \$10 million for FY 2018-19. We believe \$10 million is likely not sufficient to fully fund the Program and have expressed our concerns to DWR and the Central Valley Flood Protection Board.

Annual Maintenance – Attached are the current maintenance items we are tracking.

Special Projects – The District submitted a full application for a project under DWR's 2016 Projects Solicitation Package (PSP) for Multi-Benefit Projects. The full application proposed a project between Stations 500 and 540 that would create a habitat bench and set the levee back, while also relocating the District's Camp 5 pump station, moving it further landward. Subsequently, we requested an expansion of the project area to include rehabilitation from Stations 540-550. We have received a funding agreement for the work, and DWR has responded to our inquiry about eligibility of relocating the pump station. Removal of the existing pump station is an eligible cost (95% State share), and the new pump station will be eligible for 50% State share.

We have submitted a Full Proposal for a Directed Action project to rehabilitate the north levee. DWR is currently reviewing the proposal, and DWR has indicated that sufficient funding may not be available at this time. In response, we submitted a letter to the Delta Levees Program notifying the Program that the District believes the Directed Action project should have higher priority than the multi-benefit project.

Five Year Plan – We have received a fully executed funding agreement for the Five-Year Plan (FYP). We have started work on the Plan update and have received an advance of funds in the amount of \$26,250.00.

RD 756

Engineer's Report

Page 2

SB 88 – Work under Phase 2 of the measurement experiment (work plan for 2019) is progressing and coordination with the Delta Measurement Experimentation Consortium continues. Eight of the nine existing test sites appear to be functioning properly and collecting flow data.

Siphon logs for calendar year 2018 have been summarized and were used for water right reporting calculations. 2019 siphon logs have been received for the month of May and collection of June logs is in progress. Site visits were limited during the month due to non-use of siphons. Portable meter testing is scheduled to continue during the irrigation season.

Site visits were conducted on Bacon Island on 6/14/19 and 6/27/19 to troubleshoot and replace various sensors. Site visits were conducted on Bouldin Island on 6/6/19 and 6/21/19 to continue troubleshooting various sensor related issues including loss of power, corrosion, and communications related issues. The new flow meters recently ordered are in the process of being delivered and installed.

Reclamation District No. 756 Bouldin Island Issue Tracking Summary

7/8/2019

| IssueID | Priority | Report Date | Reporter | Location | Issue Type | Description | Action | Field Notes |
|---------|----------|-------------|--------------------|-----------------|--------------|---|---------|--|
| 23 | Low | 2/11/2017 | JaimeBarajas | Station 859 | Boil | Boil on lower levee slope/toe; running at high tide | Monitor | 25 LF core trench along WS hinge to depth of 8'; no pipe or water encountered; backfilled with native material. |
| | | 2/44/2047 | | | | Boil on lower levee slope/toe; running at high | | 40 LF core trench along WS hinge to depth of 8'; encountered water seeping from landside trench wall at 8' depth; backfilled with native and imported dry fill; Drainage ditch to be cut along Caltrans access roadway from Sta 926 to Sta 2 to relieve ponding. Work to be done by Sierra |
| 24 | Low | 2/11/2017 | JaimeBarajas | Station 924+10 | Boil | tide | Monitor | Cattle. 8/14/17 - Waterside top of |
| 34 | Low | 2/20/2017 | NateHershey | Station 813 | Encroachment | Siphon may be low | Monitor | pipe = 7.2; 100 yr. flood = 7.6; 12" siphon; pipe is low; Continue to Monitor |
| 41 | Medium | 3/28/2017 | , RalphHeringer | Station 544-549 | Crack | Cracking in LS Slope; seepage and cattails at toe | Monitor | Monitor and discuss repair; 10/23/17 Levee crown trenched; no encroachments located, Area to be graded and prepared for flood season; will proceed under Special Projects upon receipt of PFA. 12/4/17 - grading complete |
| 53 | Medium | 8/11/2017 | NateHershey | Station 324 | Seepage | Seepage at toe of 3 to 1 slope | Monitor | Monitor |

Reclamation District No. 756 Bouldin Island Issue Tracking Summary

7/8/2019

| IssueID | Priority | Report Date | Reporter | Location | Issue Type | Description | Action | Field Notes |
|---------|----------|-------------|------------------|------------------|----------------|-------------------------------|-------------|-----------------------------------|
| | , | • | • | | ,, | | | Monitor; The hole is shallow at |
| 54 | Medium | 8/11/2017 | NateHershey | Station 336 | Seepage | | Monitor | about 1-2 inches deep. |
| | | | | | | | | |
| | | | | | | Longitudinal crack on land | | |
| | | | | | | side slope near toe of | | Investigate and monitor; It's |
| | | | | | | Levee. Crack runs several | | clear to me that there is |
| | | | | | | hundred feet parallel to | | differential settling after slope |
| 63 | Medium | 3/23/2018 | RussRyan | Station 72 | Crack | Levee road. See photos. | Repair | vegitation was cleared. |
| | | | | | | | | |
| | | | | | | Adjacent to Duck Club | | |
| | | | | | | office on Levee slope water | | Min. Fill material;Need to |
| | | | | | | side. Appears to be | | investigate extent of hole and |
| | | | | | | possible Beaver Den | | fill in with Levee backfill |
| 65 | Medium | 5/8/2018 | RussRyan | Station 710 | RodentActivity | discovery during low tide. | Repair | material/rock. |
| | | | | | | Possible beaver den by | | Two levee penetrations, one |
| | | | | | | district office, west of tree | | on top of other. WS slope |
| 65.1 | Medium | 6/19/2018 | AndrewReece | Station 712+00 | RodentActivity | on ws slope | Repair | sloughing. |
| | | | | Land side within | | Bouldin Island - West | | |
| | | | | 150 foot Levee | | stretch length adjacent to | | |
| | | | | footprint. See | | Mokelumne River. See | | |
| | | | | attached phots. | | attached photos for exact | | |
| 74 | Low | 1/5/2019 | RussRyan | Low wet areas. | Other,Sinkhole | location. | Investigate | See notes above. |
| | | | | | | sloughing on water side for | | |
| | | | | | | about 100 feet, cracking at | | |
| 85 | Low | 4/1/2019 | MichaelNishimura | 79+00-80+00 | Sloughing | hinge | Monitor | |

Reclamation District No. 756 Bouldin Island Issue Tracking Summary

7/8/2019

| IssueID | Priority | Report Date | Reporter | Location | Issue Type | Description | Action | Field Notes |
|---------|----------|-------------|-----------------|---|------------|--|-------------|--|
| 0.0 | Modium | F /7/2010 | Duinn lan quink | Sta 845+00 to 846+00 between toe road and | Saanasa | Seepage between toe road and seepage ditch appeared last week. Does not appear to be tidally influenced and a point source was not located. Additional minor wet spots observed between Sta 841+00 and 843+00. No known history of seepage | Donair | District (Dave, Russ, Ralph) to review site on 5/10. Exploratory trenching will likely be required. Perform trenching when convenient as long as site does not change or |
| 86 | Medium | 5/7/2019 | BrianJanowiak | seepage ditch | Seepage | at this location. | Repair | worsen. |
| 86.1 | | 5/10/2019 | | | | | | Looks like seepage is drying up. |
| 88 | | 6/7/2019 | DaveForkel | Sta 382+00 | Seepage | Seepage on side of levee. | Investigate | |